


10/015634
1/23 29 HGS


FIG. 1



10015634-121701

(FRONT SIDE)


FIG. 3



(REAR SIDE)

(FRONT SIDE)


FIG. 5



10015634.121701

FIG. 6

FIG. 7



[illegible]

FIG. 9





FIG. 10



10015634.121701

FIG. 11





FIG. 12 (a)



PAPER TRANSFER CENTER
FIG. 12 (b)




FIG. 13 (a)




FIG. 13 (b)




FIG. 15





FIG. 16



10015634.121701

FIG. 17




FIG. 18 (a)





FIG. 18 (b)



10015634, 121701

FIG. 19 (a)





FIG. 19 (b)



10015634-121701

FIG. 20

FRONT JOGGER: ARRANGING MEMBER 102a
REAR JOGGER: ARRANGING MEMBER 102b






FIG. 21




10015634.121701
TOTAL TESTS

FIG. 22



10045634-121701
TOP LEFT TEST FOOT

FIG. 23



10015634.121701

FIG. 24




FIG. 25

